

Superlift Catalog #115 Corrections

Page Number	Description	Date
Chevrolet		
Pg. 69	The Chevy / GMC SUV 3/4 Ton 4wd Avalanche, Suburban application should read 2000-07	1/9/2008
Pg. 83, 97, 115, 125	All K kits and kit boxes assigned to vehicles with "Electronic Controlled Shocks" are DISCONTINUED.	2/13/2008
Pg. 84, 85, 98, 99, 106, 107, 109, 116, 117, 126	All 2007 applications for Chevy / GMC 1500, 2500, 2500HD, 3500, Avalanche, Tahoe, and Suburban now apply to the 2008 models.	2/13/2008
Pg. 9	Tire and Wheel Information - Both 6" Knuckle Applications should read: Minimum Backspacing 5.5", Maximum Backspacing 6". Disregard the *Note.	7/9/2008
Pg. 236	The GM Pickup 1/2 Ton application for 1999-2007 should read 1999-2006; the 2580 does not fit 2007 pickups.	3/26/2008
Dodge		
Pg. 63	Pickup - Ram 1500 1/2 Ton 4wd 2006-07 now applies to the 2008 models.	3/3/2008
Pg. 131	Pickup - Ram 1500 1/2 Ton 4wd 2006-07 now applies to the 2008 models.	2/13/2008
Pg. 136, 137, 138, 139	Options for "Carrier Bearing Relocator" should be 4668 Carrier Bearing Shim kit	7/17/2008
Ford		
Pg. 37	The Super Duty lift chart should not include a 1" coil spacer options as Superlift does not offer this kit.	2/15/2008
Pg. 70	Ford F250 / F350 Super Duty Torque Max application chart should read 2005 - 2007. 2008 application should read as follows: Extended cab & Crew cab long bed 20520 (Standard) and 20525 (Select Series); Extended cab short bed 20500 (Standard) and 20505 (Select Series); Crew cab short bed 20510 (Standard) and 20515 (Select Series).	2/19/2008
Pg. 158	F150 2wd & 4wd 2004-07 Level-it -- Optional Rear SS-Bilstein shock number BE5-5246-H5 is replaced by BE5-6249-H5.	2/12/2008
Pg. 158	F150 2wd & 4wd 2004-07 now applies to the 2008 models.	2/13/2008
Pg. 155	F150 2wd 1980-96 K534 & K538 list coil spring # 130 - it should be # 131	5/15/2008
Pg. 164, 167, 171	All F250 / F350 Superduty 1999-2004 3" kits have been DISCONTINUED.	5/15/2008
Pg. 175	Optional track bar bracket part number 9063 is replaced by 9019.	2/12/2008
Pg. 177	Optional torque max standard and select series part numbers have changed ; 20400 should be (=) 20500, 20410 = 20510, 20420 = 20520, 20405 = 20505, 20415 = 20515, 20425 = 20525.	2/12/2008
Pg. 177	Optional multi-shock front kit part number 60130 is replaced by 60132.	2/12/2008
Pg. 179, 180, 181, 182	Part number 92730 - Dual Steering Stabilizer Kit - SS (Stainless) should be added to the optional steering stabilizer section.	2/13/2008
Pg. 181	The optional front bulletproof brake hose is included in the kit box and should not be listed as an option.	2/12/2008
Pg. 182	F250 / F350 Super Duty 4wd 2008 ALL 8" and 10" applications MUST order a dual steering stabilizer from the following two options 92694 (dual standard kit) or 92730 (dual SS stainless kit) -- THE FACTORY STEERING STABILIZER WILL NOT WORK.	2/13/2008
Pg. 184	K665 kit has a part number ###; this should be 1738.	7/9/2008
Pg. 230	F250 / F350 Super Duty 4wd 2005-08 should be 2005-07. The 2008 bracket part number is 60132.	7/9/2008
Pg. 232	Ford F250 and F350 year split should be 2005-07 with 92693 (dual standard kit) - 92690 (dual flame kit) - 92730 (dual ss stainless kit) -- 2008 92694 (dual standard kit) - 92730 (dual ss stainless kit)	2/7/2008
Pg. 241	Ford F250 / F350 Super Duty year split should be 2005-07 4-8" 91520 (Front Bulletproof) - 91515 (Rear Bulletproof) --- 2008 2-4" 91540 (Front Bulletproof) - 91515 (Rear Bulletproof) --- 6-10" 91560 (Front Bulletproof) - 91515 (Rear Bulletproof)	2/13/2008

Superlift Catalog #115 Corrections

Page Number	Description	Date
Jeep		
Pg. 208	2" JK Options - Front Lower Link Arms, RockRunner Options and Adjustable Track Bars need to be removed. These options will not work with a 2" kit.	5/21/2008
Pg. 222	Jeep Wrangler JK 2007-08 applications are as follows: Front SS # 97020 - Rear SS # 97019 and Front SSR # 95026 (120) - Rear SSR #95028 (120)	2/13/2008
Pg. 266	Jeep Wrangler TJ 1997-06 3" AT Front Shock should be 857059.	8/8/2008
Pg. 267	JK Options missing notes -- Part # 716240 (151, 152) - Part # 700613 (151, 152) -- Note 151...If JK 2" lift requires additional caster, order cams, part number 716241. 152...If JK 3" lift requires additional caster, order your choice of either fixed-length links or XT links.	2/12/2008
Pg. 267	JK Wrangler 2 & 4 Door 2007-08 3" suspension should have note 152..If JK 3" lift requires additional caster, order your choice of either fixed-length links or XT links.	2/12/2008
Pg. 267	JK Options missing part number -- Part # for Alignment Cams; Front Caster / Pinion Angle is 716241	2/12/2008
Pg. 269	Jeep Wrangler TJ 1997-06 should be 1-2" (Frt. 857059 - Rr. 857014) and 3" (Frt. 857059 - Rr. 857022)	8/8/2008
Toyota		
Pg. 217	4-Runner 2wd & 4wd 1996-02 2-1/2" applications have been DISCONTINUED.	2/12/2008
Pg. 220	Sequoia 2wd & 4wd 2001-03 applications have been DISCONTINUED.	2/12/2008
Pg. 220	Tundra 2wd & 4wd 1999-2006 2" application shows K827; should be K752.	3/31/2008